

171025
J.L. CLARK Manufacturing Co. Containers & Specialties of Lithographed Metal, Metal-Plastic or Plastic

ATLAS TUBE DIVISION 2300 WISCONSIN AVE., DOWNERS GROVE, ILL. 60515 PHONE 312 969-6100

October 11, 1971


gc
JL 10/15/71
Mr. James J. Cervinka
Vice President
Arrow Gear Company
2301 Curtiss Street
Downers Grove, Ill. 60515

Dear Mr. Cervinka,

As indicated in our telephone conversation we were in the process of diverting the water drainage to the Northwest corner of our property. The connections for diverting this water are complete.

The rain water drainage will still continue to drain to this corner but this is not the water that prompted your concern.

Sincerely,


Richard A. Anderson
General Manager

RAA/nld

October 5, 1971

Mr. Richard Anderson, General Manager
Atlas Tube Division
J. L. Clark Manufacturing Company
2300 Wisconsin
Downers Grove, Illinois 60515

Dear Mr. Anderson:


I would like to confirm your telephone call to me on September 17, 1971, wherein you indicated you were going to make some changes and run some of your discharge water into the Downers Grove sewer system instead of the drain pipe emptying on the northwest corner of your property.

Please advise me when this is completed so that we may inspect the change.

Might I suggest, if possible, diverting all of that water into the sanitary sewers and eliminating this problem altogether.

I am sure that at some date, if we build in this area, it would have to be cut off.

Very truly yours,



James J. Cervinka
Vice President

JJC:oj

September 9, 1971

Mr. Richard Anderson, General Manager
Atlas Tube Division
J. L. Clark Manufacturing Company
2300 Wisconsin
Downers Grove, Illinois 60515

Dear Mr. Anderson:

I would like to call to your attention a sewer discharge pipe on the northwest corner of your property. This pipe originally was discharging a small amount of cooling water when your plant was originally constructed.

At that time we permitted this as long as the amounts were not too great and it was only water. I have had occasion to observe this over the past few months, and it seems that we are getting quite increased amounts of water plus oil and seemingly other fluids.

I would like you to look at this and advise us what steps can be taken to correct the situation in the near future. Please feel free to call me should you have any questions.

Very truly yours,

ARROW GEAR COMPANY


Jim Cervinka
Vice President

JJC:oj

*called
me 9/17/71*

ATLAS TUBE DIVISION
J. L. CLARK MFG. CO
2300 Wisconsin
Downers Grove, Illinois 60515

Mr. Richard Anderson, General Manager

(President is Russell Gibson at main plant in Rockford.)